Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080147-1

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11556

RECEIVED FROM PLANT 99

DATE REC'D 3-11-57
P.O. NO.
VENDOR PACKING SLIP NO.

	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
CHARGE TO	322		015	C	21					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
65	738235-2 Flange Asbly Spool IPS #04738	65	✓	

RECEIVED BY J Barcelos
INSPECTED BY Dula
DATE 3/11/57
REJECTS RETURNED ON SHIP MEMO NO.

HMC-1059

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11559

RECEIVED FROM Milli Switch Corp.

DATE REC'D 3-12-57
P.O. NO. 69505
VENDOR PACKING SLIP NO. 13307

	CONTRACT CODE NO	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
CHARGE TO	322	000006	89	F	23	1				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
54	730129-26 Switch-Milli / Switch Cat. #B2	54	✓	

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080147-1

RECEIVED BY Barcelos
INSPECTED BY Dula
DATE 3/12/57
REJECTS RETURNED ON SHIP MEMO NO.